

## Material Safety Data Sheet

Section 1: Company Information	
Product: Fly Ribbon Part #: SI2000, SI2010	
Manufacturer: The Coburn Company, Inc.  Address: PO Box 147 Whitewater, Wisconsin 53190	Emergency Telephone Number : 262 473 2822  Telephone Number for Information: 262 473 2822  Fax: 262 473 3522  Data Prepared: April 22, 2016

Section 2: Substance Information	
Composition Adhesive Sheet: Paper Adhesive: Pressure Sensitive Adhesive, Rosin Resin, Petroleum Resin Container: Paper Push pin: Metal Cover: Paper	
Chemical Characteristics (Chemical Formula or Structure)	N/A
CAS No.	N/A
Hazardous Component	N/A
Hazardous Contamination	N/A

Section 3: Hazardous Information	
Health Hazards	N/A
Environment Hazards	N/A
Combustibility	Flammable

Section 4: First Aid Measures	
Route of Entry:	To Be Taken in First-Aid
Inhalation	Will Not Case

Skin	Wash with Water, If Needed See Dermatologist
Eyes	Wash with Running Water, If Needed See Ophthalmologist
Ingestion	Vomit Out, If Needed See Doctor

Section 5: Fire and Explosion Hazard Data	
Extinguishing Media	Water, Dry Chemical Form, Dry Chemical Powders or Carbon Dioxide May Be Useful
Must Not Use as Extinguishing Media	N/A
Special Fire Fighting Procedures	Use the Extinguishing Media Above
	Wear Self-contained Breathing apparatus and Protective Clothing to Prevent Smoke Contact with Skin and Eyes

Section 6: Precautions	
For Safe Handling and Use	Avoid contact with adhesive for extended period of time
For Storing	Avoid Sunlight, High Temperature, High Humidity and Water

Section 7: Physical / Chemical Characteristics	
Physical Appearance	
Odor	N/A
pH	N/A
Boiling Point	N/A
Melting Point	N/A
Decomposition Temperature	N/A
Flash Point	N/A
Ignition Point	N/A
Explosion Hazard Data	
Explosive Limit	N/A
Vapor Pressure	N/A
Vapor Density	N/A

Density	N/A
Solubility	
In Water	Hard
In Organic Solvent	Easy to Adhesive

Section 8: Safety and Reactivity Data	
Stability	Stable in Normal Condition

Section 9: Waste Disposal Method	
Use Approved Disposal Methods as Recommended by State and Local Agencies	

Section 10: Cautions in Transport	
Avoid High Temperature, High Humidity, Sunlight, Water	
Avoid Falling Sideways, Dropping, Dragging	

Section 11: Other Precautions	
N/A	